

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

RECEIVED

APR - 8 1991

O. C. D.

ARTESIA, NM

(505) 748-1471

5. Lease Designation and Serial No.

NM 045274

6. If Indian, Allottee or Tribe Name

N/A

7. If Unit or CA, Agreement Designation

N/A

8. Well Name and No.

Hill View AHE Federal Com #7

9. API Well No.

10. Field and Pool, or Exploratory Area

South Dagger Draw Upper Penn

11. County or Parish, State

Eddy, New Mexico

12 CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
- ☐ Subsequent Report
- ☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
- ☐ Recompletion
- ☐ Plugging Back
- ☐ Casing Repair
- ☐ Altering Casing
- ☒ Other Spud, Set Surface

- ☐ Change of Plans
- ☐ New Construction
- ☐ Non-Routine Fracturing
- ☐ Water Shut-Off
- ☐ Conversion to Injection
- ☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded 26" hole 11:30 AM 3-12-91. Notified Dan Early, BLM, Carlsbad, NM of spud. Resumed drilling 14-3/4" hole 7:45 PM 3-14-91. Notified BLM Answering Service, Carlsbad, NM. Ran 28 jts 9-5/8" 36# J-55 casing set 1215'. Guide shoe set 1215', insert float set 1172'. Cemented w/900 sx Pacsetter Lite w/10#/sx Gilsonite, 1/2#/sx Celloseal, 3% CaCl₂ (yield 1.88, wt 14.8). Tail in w/200 sx Class "C" w/2% CaCl₂ (yield 1.32, wt 14.8). PD 4:15 AM 3-18-91. Bumped plug to 1000 psi, float held okay. Cement did not circulate. WOC 5 hrs. Ran Temp. Survey and found top of cement 136'. Ran three stages of 1". Cemented with 425 sx Class "C" with 4% CaCl₂. Circulated 5 sacks to pit. PD 2:50 PM 3-18-91. WOC. Drilled out 10:15 PM 3-18-91. WOC 18 hrs. NU and tested to 1000 psi for 30 minutes, OK. Reduced hole to 8-3/4" and resumed drilling.

ACCEPTED FOR RECORD

APR 8 1991
SJS

CARLSBAD, NEW MEXICO

14. I hereby certify that the foregoing is true and correct

Signed [Signature]Title Production SupervisorDate 3-29-91

(This space for Federal or State office use)

Approved by _____
Conditions of approval, if any:

Title _____

Date _____

ACCEPTED FOR RECORD

10/28/80