

WELL NAME AND NUMBER East Millman Unit 7-13  
LOCATION 2176' FSL, 177' FWL, Sec. 13, T19S, R28E, Eddy Co. NM  
OPERATOR Stephens & Johnson Operating Co.  
DRILLING CONTRACTOR United Drilling, Inc.

The undersigned hereby certifies that he is an authorized representative of the drilling contractor who drilled the above described well and had conducted deviation tests and obtained the following results:

<u>Degrees @ Depth</u>	<u>Degrees @ Depth</u>	<u>Degrees @ Depth</u>
<u>1° @ 496'</u>	<u>                    </u>	<u>                    </u>
<u>1° @ 1009'</u>	<u>                    </u>	<u>                    </u>
<u>3/4° @ 1499'</u>	<u>                    </u>	<u>                    </u>
<u>1/2° @ 2013'</u>	<u>                    </u>	<u>                    </u>
<u>3/4° @ 2412'</u>	<u>                    </u>	<u>                    </u>
<u>                    </u>	<u>                    </u>	<u>                    </u>
<u>                    </u>	<u>                    </u>	<u>                    </u>
<u>                    </u>	<u>                    </u>	<u>                    </u>

Drilling Contractor United Drilling, Inc.

By: George Aho *George A. Aho*

Title: Business Manager

Subscribed and sworn to before me this 6th day of June,  
20 01.

*Carlene Martin* Carlene Martin  
Notary Public

My Commission Expires: 10-04-04

Chaves, New Mexico  
County State