

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRI  
(Other instruction. on re-  
verse side)

Form approved.  
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		5. LEASE DESIGNATION AND SERIAL NO. LC-065347
2. NAME OF OPERATOR Gulf Oil Corporation		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P. O. Box 670, Hobbs, NM 88240		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 2310' from north line and 2310' from west line Section 28, T-24-S, R-26-E		8. FARM OR LEASE NAME White City Penn Gas Com Unit 3
14. PERMIT NO.		9. WELL NO. 1
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3393' GL		10. FIELD AND POOL, OR WILDCAT White City Penn
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 28 24-S 26-E
		12. COUNTY OR PARISH Eddy
		13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		<input type="checkbox"/>

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	<input checked="" type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOTING OR ACIDIZING	<input type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		<input type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Reached TD 8337' of 9-1/2" hole December 1, 1976.  
Ran 184 jts and 1 cut jt 8316' of 7-5/8" OD 26.40#, S-95 buttress casing.  
Set at 8336'. Cemented with 200 sacks thick set, 400 sacks lite with 5% CFR-2 and 300 sacks Class H 15% CFR-2.  
WOC 54-1/2 hours. Temperature survey indicated top of cement at 2950'.  
Tested 7-5/8" casing with 3000# 30 min - OK.  
Started drilling 6-1/2" hole at 8337' at 10:15 PM 12-4-76.

RECEIVED

DEC 6 1976

GEOLOGICAL SURVEY  
ARRESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED G. F. Berlin TITLE Area Engineer DATE 12-6-76

(This space for Federal or State office use)

APPROVED BY Joe J. Lars TITLE ACTING DISTRICT ENGINEER DATE DEC 13 1976  
CONDITIONS OF APPROVAL, IF ANY: