

9. Well Site Layout

- A. The wellsite and 400 ft X 400 ft surrounding area have been surveyed and flagged.
- B. Dimensions and relative location of the drill pad, pit, and equipment are shown on Exhibits 'A', 'B', and 'G'.
- C. Top soil for the restoration will be stock-piled on the north and east sides of the location.

10. Plans for Restoration of the Surface

- A. After completion of drilling, completion, and construction operations, all equipment and other material not needed for operations will be removed. Pits will be filled and the location cleaned of all trash and junk so as to leave the wellsite in an as aesthetically pleasing condition as possible.
- B. Any unguarded pits containing fluids will be fenced until they are filled.
- C. If the well is not productive, the disturbed area will be restored to Federal Agency requirements and will be accomplished as expeditiously as possible.

11. Surface Ownership

The road, location, and all construction will be on Public land.

12. Other Information

- A. **Topography:** The location is located on a slight ridge near some low mounds or hills in an essentially featureless area. The land rises to the west and overall drainage is generally to the east. A more technical description will be included in the archaeological report.
- B. **Soil:** A technical description of the soil will be included in the archaeological report.
- C. **Flora and Fauna:** The vegetation is sparse and will be fully described in the archaeological study. No wildlife was observed. Probably rodents, other small animals, and reptiles inhabit the area.
- D. **Pond or Streams:** There are no pond or streams within one mile.
- E. **Residences and Other Structures:** There are no known inhabited structures or residences within one mile of the location.
- F. **Archaeological, Historical, and other Cultural Sites:** An archaeological survey of the well pad and road has been or will be done in the very near future by Desert West Archaeological Services, Carlsbad, NM. A copy of their report will be delivered to the Bureau of Land Management, Carlsbad Resource Area Office as soon as it is available.
- G. **Land Use:** No livestock were seen and there was no evidence of grazing. The land appears to be essentially idle.