

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instruct on reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 020200 A 052 4

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Guadalupe Ridge Unit

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

22-T26S-R21E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	
2. NAME OF OPERATOR SINCLAIR OIL CORPORATION	
3. ADDRESS OF OPERATOR P. O. Box 1920, Hobbs, New Mexico 88240	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' from the West line and 660' from the North line	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Run & cement 7"OD casing

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

12-19-68 Depth 5195'. Ran electric logs.

12-20-68 Ran 7"OD 23# J-55 & N-80 F.J. casing set @ 5194' and cemented w/100 sacks Cl. H cement, 0.75% CFR-2, 10#/sk Gilsonite, 0.25#/sk. Flo-seal. Slurry Wt. 15.8#/gal. Ran temperature survey, top of cement @ 4200' from surf. WOC 24 hrs.

12-23-68 Pressure tested casing to 800# for 30 mins. Tested O.K.

RECEIVED

DEC 27 1968
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

RECEIVED

DEC 30 1968

O. C. C.
ARTESIA, OFFICE

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Superintendent

DATE 12-26-68

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

APPROVED

DEC 27 1968
R. L. BECKMA

Orig'd cc: USGS, Artesia

cc: Southern Region (West Texas)

cc: Mrs. M. M. Rhea, Santa Fe, New Mexico

cc: Parsons, cc: File

*See Instructions on Reverse Side