

N. M. O. C. C. COPY,

Form 9-831a
(Feb. 1951)

(SUBMIT IN TRIPLICATE)

Land Office _____

Lease No. LC 063875

Unit _____

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

RECEIVED

OCT 20 1960

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 14, 1960

No. 9 Fisher Lake Unit A-5
Well No. _____ is located 660 ft. from N line and 660 ft. from E line of sec. 23

SE 1/4 of the NE 1/4 Sec. 23
(1/4 Sec. and Sec. No.) 35E 36E 7
(Twp.) (Range) (Meridian)
Wildcat 564 New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 2314 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

3 5/8" Surface Casing cemented at 552' with 150 sacks cement.
Cased: 2967' - 4037'

4006 - 4008, 4013 - 4013, 4016 - 4019, slight shows lost
7 3/4 212 and sub in hole at 4032'

Plugged:
@ Surface - 3 sacks
@ Base of Surface Casing, 305'-570', 20 sacks
@ 3005-3070, 20 sacks

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Alamo Corporation, Agents for Richardson & Ross

Address 1004 Lubbock Nat'l Bank Bldg.
Lubbock, Texas

By L. E. Jackson

Title Representative