

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	Southern Union Gas Services, Ltd.	Contact	Tony Savoie
Address	P.O. Box 1226 Jal, N.M. 88252	Telephone No.	505-395-2116
Facility Name	Lea County Field Dept.	Facility Type	Natural Gas Gathering
Surface Owner: Dinwiddie	Mineral Owner: Federal	Lease No.	


LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	11	26S	33E					Lea

Latitude N32 3.911 Longitude W103 32.949

NATURE OF RELEASE

Type of Release : Natural Gas and produced water	Volume of Release: 236 MCF Nat. Gas < 5 bbls of produced water.	Volume Recovered 0
Source of Release : 16" Natural Gas Pipeline	Date and Hour of Occurrence Not Known	Date and Hour of Discovery 5/8/07 Time: 9:30 a.m..
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Gary Wink	
By Whom? Buddy Hill	Date and Hour: 5/8/07 10:00 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	



If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A 16" Natural Gas pipeline operating at approximately 35 PSI developed a leak. The line was shut in and blown down approximately 333 mch of natural gas was released during the blow-down event. There was no H2S observed being released during the leak assessment or the blow down event.

Describe Area Affected and Cleanup Action Taken. The affected area measured approximately 30 ft. by 40ft. of pasture land and right-of-way road. The damaged pipe will be replaced 5/9/07 and the affected area will be remediated in accordance to the NMOCD guidelines for leaks and spills.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>	OIL CONSERVATION DIVISION	
Printed Name: John A. "Tony" Savoie	Approved by District Supervisor: <i>[Signature]</i>	
Title: Remediation Supervisor	Approval Date: 5.22.07	Expiration Date: 7.22.07
E-mail Address: tony.savoie@sug.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 5/9/07 Phone: 505-395-2116	SUBMITAL OF FINAL C-141 BY	

* Attach Additional Sheets If Necessary

W/ ALL SURVEYING DATA ATTACHED

incident - PAC0714240422
application - PAC0714240539

RP# 1309