

Summary Report

Thomas Franklin
APEX/Titan
2351 W. Northwest Hwy.
Suite 3321
Dallas, Tx 75220

Report Date: November 24, 2014

Work Order: 14112101



Project Location: Lea County, NM
Project Name: Regency/RR Sims 10" MA-3 Line
Project Number: 7030714G099

Sample	Description	Matrix	Date Taken	Time Taken	Date Received
380215	NW Side Wall	soil	2014-11-20	11:27	2014-11-20
380216	Bottom Hole West	soil	2014-11-20	11:27	2014-11-20
380217	SE Side Wall	soil	2014-11-20	12:12	2014-11-20
380218	Bottom Hole East	soil	2014-11-20	12:14	2014-11-20

Sample - Field Code	BTEX				TPH DRO - NEW	TPH GRO
	Benzene (mg/Kg)	Toluene (mg/Kg)	Ethylbenzene (mg/Kg)	Xylene (mg/Kg)	DRO (mg/Kg)	GRO (mg/Kg)
380215 - NW Side Wall	<0.0200	<0.0200	<0.0200	<0.0200	<50.0	<4.00
380216 - Bottom Hole West	<0.0200	<0.0200	<0.0200	<0.0200	<50.0	<4.00
380217 - SE Side Wall	<0.0200	<0.0200	<0.0200	<0.0200	<50.0	<4.00
380218 - Bottom Hole East	<0.0200	<0.0200	<0.0200	<0.0200	<50.0	<4.00

Sample: 380215 - NW Side Wall

Param	Flag	Result	Units	RL
Chloride		<20.0	mg/Kg	4

Sample: 380216 - Bottom Hole West

Param	Flag	Result	Units	RL
Chloride		99.0	mg/Kg	4

Sample: 380217 - SE Side Wall

Report Date: November 24, 2014

Work Order: 14112101

Page Number: 2 of 2

Param	Flag	Result	Units	RL
Chloride		<20.0	mg/Kg	4

Sample: 380218 - Bottom Hole East

Param	Flag	Result	Units	RL
Chloride		99.0	mg/Kg	4
