

Summary Report

(Corrected Report)

Thomas Franklin
APEX/Titan
2351 W. Northwest Hwy.
Suite 3321
Dallas, Tx 75220

Report Date: December 1, 2014

Work Order: 14112523



Project Location: Lea County, NM
Project Name: Regency/RR Sims 10" MA-3 Line
Project Number: 7030714G099

Sample	Description	Matrix	Date Taken	Time Taken	Date Received
380703	NW Side Wall 2	soil	2014-11-25	11:05	2014-11-25
380704	SW Side Wall	soil	2014-11-25	11:00	2014-11-25
380705	SE Side Wall 2	soil	2014-11-25	10:55	2014-11-25

Sample - Field Code	BTEX				TPH DRO - NEW	TPH GRO
	Benzene (mg/Kg)	Toluene (mg/Kg)	Ethylbenzene (mg/Kg)	Xylene (mg/Kg)	DRO (mg/Kg)	GRO (mg/Kg)
380703 - NW Side Wall 2	<0.0200	<0.0200	<0.0200	<0.0200	<50.0	<4.00
380704 - SW Side Wall	0.0831	0.0758	0.0897	0.222	<50.0	<4.00
380705 - SE Side Wall 2	<0.0200	<0.0200	<0.0200	<0.0200	<50.0	<4.00

Sample: 380703 - NW Side Wall 2

Param	Flag	Result	Units	RL
Chloride		50.0	mg/Kg	4

Sample: 380704 - SW Side Wall

Param	Flag	Result	Units	RL
Chloride		250	mg/Kg	4

Sample: 380705 - SE Side Wall 2

Report Date: December 1, 2014

Work Order: 14112523

Page Number: 2 of 2

Param	Flag	Result	Units	RL
Chloride		<20.0	mg/Kg	4
