

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company Key Energy Services, LLC	Contact Bobby Sisson
Address 1301 McKinney Street, Suite 1800, Houston, TX 77010	Telephone No. 806-401-4349
Facility Name Atha SWD	Facility Type SWD
Surface Owner Dasco & McCasland	Mineral Owner Dasco & McCasland
API No. 30-025-08816	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	6	22S	36E	660'	North Line	990'	West Line	Lea

Latitude 32° 25' 47.8" N Longitude 130° 18' 36.9" W

**NATURE OF RELEASE**

Type of Release Produced Water	Volume of Release 20 bbl	Volume Recovered 20 bbl
Source of Release 500 bbl tank	Date and Hour of Occurrence 01/24/2015 0500	Date and Hour of Discovery 01/24/2015 0500
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES. To Whom? Randy Corbel	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES. Volume Impacting the Watercourse. n/a	
If a Watercourse was Impacted, Describe Fully.* Not applicable.		
Describe Cause of Problem and Remedial Action Taken.* While unloading a vacuum truck, the automated shut of system failed and the tank overflowed. The truck driver picked up free fluids with his truck.		
Describe Area Affected and Cleanup Action Taken.* Removed all fluid. Removed 20 yards of Contaminated soil from the entire contaminated area. Replaced with Clean soil. Automation system is functioning Properly.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: 	<b>OIL CONSERVATION DIVISION</b> Hydrologist	
Printed Name: Bobby Sisson	Approved by Environmental Specialist: 	
Title: Operations Manager	Approval Date: 02/03/2015	Expiration Date: 04/03/2015
E-mail Address: bsisson@keyenergy.com	Conditions of Approval: Site samples required. Deliniate and remediate area as per NMOCD	
Date: 1-27-15 Phone: 806-401-4349	Attached <input type="checkbox"/> 1RP-3522	

\* Attach Additional Sheets If Necessary

19797  
04/03/2015  
nTO1503448770  
pTO1503448904