

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company: OXY	Contact: Raymond Aguilar	
Address: 1017 W Stanolind Road	Telephone No. 575-390-6312	
Facility Name: South Hobbs Unit 29 Injection 7	Facility Type:	
Surface Owner	Mineral Owner	API No. 30-025-07620

**LOCATION OF RELEASE**

Unit Letter	Section: 5	Township: 19S	Range 38E	Feet from the	North/South Line	Feet from the	East/West Line	County:
-------------	---------------	------------------	--------------	---------------	------------------	---------------	----------------	---------

Latitude 32.691010 Longitude -103.1680

**NATURE OF RELEASE**

Type of Release: Produced Water	Volume of Release: 200BBLS	Volume Recovered: 25 BBLS
Source of Release: 3" Steel Injection	Date and Hour of Occurrence: 1-19-2015 11:00PM	Date and Hour of Discovery
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? Raymond Aguilar	Date and Hour: 1-19-2015 12:34 AM (left message)	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully \*

Describe Cause of Problem and Remedial Action Taken. \*



The cause of leak was external corrosion

Describe Area Affected and Cleanup Action Taken. \*

Safety & Environmental Solutions, Inc. will delineate the spill area and submit an appropriate work plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

**OIL CONSERVATION DIVISION**

Signature: 	Hydrologist	
Printed Name: Tony Aguilar	Approved by Environmental Specialist:	
Title: HES Specialist	Approval Date: 02/05/2015	Expiration Date: 04/05/2015
E-mail Address: Raymond_Aguilar@oxy.com	Conditions of Approval: Site samples required. Delineate and remediate area as per NMOCD guides.	Attached <input type="checkbox"/> 1RP-3526 157984
Date: <u>2-5-15</u> Phone: 575-390-6312		

\* Attach Additional Sheets If Necessary

nTO1503655515

pTO1503655642