

Summary Report

Thomas Franklin
APEX/Titan
2351 W. Northwest Hwy.
Suite 3321
Dallas, Tx 75220

Report Date: February 9, 2015

Work Order: 15020509



Project Location: Lea Co, NM
Project Name: Fullerton Drip Tank
Project Number: 7030714G044

Sample	Description	Matrix	Date Taken	Time Taken	Date Received
385976	SW-1 (N)	soil	2015-02-04	11:05	2015-02-05
385977	SW-2 (W)	soil	2015-02-04	11:02	2015-02-05
385978	SW-3 (E)	soil	2015-02-04	10:58	2015-02-05
385979	SW-4 (S)	soil	2015-02-04	10:53	2015-02-05

Sample - Field Code	BTEX				TPH DRO - NEW	TPH GRO
	Benzene (mg/Kg)	Toluene (mg/Kg)	Ethylbenzene (mg/Kg)	Xylene (mg/Kg)	DRO (mg/Kg)	GRO (mg/Kg)
385976 - SW-1 (N)	<0.0200	<0.0200	<0.0200	<0.0200	90.6	<4.00
385977 - SW-2 (W)	<0.0200	<0.0200	<0.0200	<0.0200	<50.0	<4.00
385978 - SW-3 (E)	<0.0200	<0.0200	<0.0200	<0.0200	<50.0	<4.00
385979 - SW-4 (S)	<0.0200	<0.0200	<0.0200	<0.0200	<50.0	<4.00

Sample: 385976 - SW-1 (N)

Param	Flag	Result	Units	RL
Chloride		1940	mg/Kg	25

Sample: 385977 - SW-2 (W)

Param	Flag	Result	Units	RL
Chloride		3110	mg/Kg	25

Sample: 385978 - SW-3 (E)

TraceAnalysis, Inc. • 6701 Aberdeen Ave., Suite 9 • Lubbock, TX 79424-1515 • (806) 794-1296
This is only a summary. Please, refer to the complete report package for quality control data.

Param	Flag	Result	Units	RL
Chloride		1360	mg/Kg	25

Sample: 385979 - SW-4 (S)

Param	Flag	Result	Units	RL
Chloride		1050	mg/Kg	25

preliminary summary

preliminary summary

preliminary summary

preliminary summary