

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Rice Operating Company	Contact	Katie Jones Davis
Address	122 W Taylor, Hobbs, NM	Telephone No.	575-393-9174
Facility Name	EME K-33 SWD	Facility Type	SWD

Surface Owner: Sarah Phillips Est.	Mineral Owner	API No. 30-025-21496
------------------------------------	---------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	33	19S	37E	1485	FSL	1485	FWL	Lea

Latitude 32°29'34.62" N Longitude 104°6'39.21" W

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	960 bbls	Volume Recovered	960 bbls
Source of Release	Tank	Date and Hour of Occurrence	5/16/2015 9:30 pm	Date and Hour of Discovery	5/16/2015 9:30 pm
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	Kellie Jones		
By Whom?	Katie Jones Davis	Date and Hour	5/18/2015 10:40 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

REVIEWED

By OCD District 1 at 11:41 am, May 20, 2015

Describe Cause of Problem and Remedial Action Taken.*



Lightning strike of salt water disposal system tank. The system caught fire and was extinguished. The SWD facility will be rebuilt.

Describe Area Affected and Cleanup Action Taken.*

The tanks will be removed and the liner underneath the berm will be inspected to determine integrity.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist: 		
Printed Name: Katie Jones Davis	Approval Date: 05/18/2015	Expiration Date: 08/18/2015	Attached <input type="checkbox"/> 19174 1RP-3641
Title: Environmental Project Manager	Conditions of Approval: Site samples required. Delineate and remediate as per MNOCD guides. Geotag photographs of remediation required.		
E-mail Address: kjones@riceswd.com			
Date: 5/18/2015	Phone: 575-393-9174		

* Attach Additional Sheets If Necessary

pKJ1514042504
nKJ1514042254

EME K-33 SWD (30-025-21496)
Unit Letter K, Section 33, T19S, R37E



All produced water contained within the berm
5/16/2015



EME K-33 SWD, facing south 5/16/2015



EME K-33 SWD, facing southeast 5/16/2015



EME K-33 SWD, facing east 5/16/2015



EME K-33 SWD, facing south 5/16/2015