

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: BEBIDAS STATE #002H	Facility Type: Battery

Surface Owner: State	Mineral Owner:	API No. 30-025-40855
----------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	16	23S	33E	392	South	1887	West	Lea

Latitude 32.2985593051344 Longitude -103.579673759808

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 170 bbls PW	Volume Recovered: 169 bbls PW
Source of Release: Tank Overflow	Date and Hour of Occurrence: 5/18/2015 4:30 pm	Date and Hour of Discovery: 5/18/2015 4:30 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kellie Jones – NMOCD	
By Whom? Amanda Trujillo	Date and Hour: Tue 5/19/2015 4:27 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

RECEIVED
By OCD District 1 at 12:29 pm, Jun 05, 2015

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
The release was caused when an alarm failure caused a water tank to overflow. Vacuum trucks were called to recover all standing fluid.

Describe Area Affected and Cleanup Action Taken.*
This release occurred with a lined facility. The battery was cleaned and put back into service.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: 	
Title: Senior Environmental Coordinator	Approval Date: 06/05/2015	Expiration Date: //
E-mail Address: atrujillo@concho.com	Conditions of Approval:	Attached <input type="checkbox"/> 217955
Date: June 2, 2015 Phone: 575-748-6940		IRP-3661

* Attach Additional Sheets If Necessary

nKJ1515645289
pKJ1515645447

