

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Cimarex Energy	Contact	Christine Alderman
Address	600 N. Marienfeld Ste 600 Midland TX	Telephone No.	432-853-7059
Facility Name	Cascade 29 Fed 3	Facility Type	Production
Surface Owner	Mineral Owner	Lease No. 30-025-41241	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	11	26S	32E	330	N	2310	E	Lea

Latitude 32.064165 Longitude -103.652791

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	60 bbls	Volume Recovered	0
Source of Release	flowline	Date and Hour of Occurrence	3-29-15	Date and Hour of Discovery	3-29-15
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Doc Oberding/Sol Hughes		
By Whom?	Christine Alderman	Date and Hour	3-30-15 3:53 p.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					

RECEIVED

By OCD District 1 at 3:24 pm, Jun 09, 2015

Describe Cause of Problem and Remedial Action Taken.*

It appeared that a backhoe (not hired by Cimarex) had driven through the pasture and ran over our line causing it to rupture.

Describe Area Affected and Cleanup Action Taken.*

The fluids impacted an area approximately 75'x60' in pasture area. Diversified Field Services excavated the spill area to 4' bgs and backfilled with fresh topsoil. A BLM approved seed mix was then applied to the area, restoring it to its previous state.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Christine Alderman</i>	OIL CONSERVATION DIVISION		
Printed Name: Christine Alderman	Approved by District Supervisor: <i>K. D.</i>		
Title: ESH Supervisor	Approval Date: 06/09/2015	Expiration Date: //	
E-mail Address: calderman@cimarex.com	Conditions of Approval: //	Attached <input type="checkbox"/> 1RP-3590	
Date: 5/28/15	Phone: 432-853-7059		

* Attach Additional Sheets If Necessary