

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company: <b>Devon Energy Production Co LP (6137)</b>	Contact: <b>Danny Velo, Foreman</b>
Address: <b>PO Box 250 Artesia, NM 88211</b>	Telephone No. <b>575- 703-3360</b>
Facility Name: <b>Thistle Unit 71H</b>	Facility Type : <b>Well location</b>

Surface Owner: <b>State</b>	Mineral Owner: <b>State</b>	API No. <b>30-025-42425</b>
-----------------------------	-----------------------------	-----------------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<b>A</b>	<b>27</b>	<b>23S</b>	<b>33E</b>	<b>200</b>	<b>North</b>	<b>632</b>	<b>East</b>	<b>Lea</b>

Latitude: **32deg 16' 56.123" N** Longitude: **103deg 33' 11.643" W**

**NATURE OF RELEASE**

Type of Release: <b>Frac Chemical "B-10"</b>	Volume of Release: <b>330 Gals</b>	Volume Recovered: <b>1 - 1 1/2 bbl</b>
Source of Release: <b>Chemical Tote</b>	Date and Hour of Occurrence <b>6/9/2015, 2:15 AM</b>	Date and Hour of Discovery <b>6/9/2015, 2:15 AM</b>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>OCD Hobbs - Kelly Jones</b>	
By Whom? <b>Brett Fulk, Devon EHS Professional</b>	Date and Hour: <b>6/9/2015, 4:20 PM</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. <b>NA</b>	
If a Watercourse was Impacted, Describe Fully.* <b>NA</b>	<div style="border: 2px solid blue; padding: 5px; display: inline-block;"> <p><b>RECEIVED</b> By OCD District 1 at 2:24 pm, Jun 11, 2015</p> </div>	
Describe Cause of Problem and Remedial Action Taken.* <b>A Frac Tech Services employee was unloading a chemical tote from a truck float when one of the blades on the forklift punctured the tote, spilling 330 gallons of B-10 chemical on to the ground staying on location.</b>		

Describe Area Affected and Cleanup Action Taken.\*  
**An area of approximately 15' x 15' on location was affected, located on the NW corner of the pad. A vacuum truck was used immediately and 1 to 1 1/2 barrels of chemical was recovered from the pad. A plan of remediation will be submitted at a later date for approval.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Denise Menoud</b>	Approved by Environmental Specialist: 	
Title: <b>Field Admin Support</b>	Approval Date: <b>06/11/2015</b>	Expiration Date: <b>09/09/2015</b>
E-mail Address: <b>Denise.Menoud@dvn.com</b>	Conditions of Approval: <b>Site samples required. Delineate and remediate as per MNOCD guides. Geotag</b>	Attached <input type="checkbox"/> <b>6137</b> <b>IRP-3667</b>
Date: <b>6/10/2015</b> Phone: <b>575-746-5544</b>	<b>photographs of remediation required.</b>	

\* Attach Additional Sheets If Necessary

nKJ1516252913  
pKJ1516253256

# THISTLE UNIT 71H



This map is for illustrative purposes only and is not intended to be used as a legal document. It is not intended to be used as one. Devon makes no warranty, expressed or implied, regarding this map.

WGS\_1984\_Web\_Mercator\_Auxiliary\_Sphere  
 Prepared by:  
 Map is current as of: 10-Jun-2015



- Project Outline**
- Upcoming State Lease
  - Upcoming Federal Lease Sale
  - One Year State Lease Sale Results
  - \$0.00
  - \$0.01 - \$1,020
  - \$1,020.01 - \$2,500
  - \$2,500.01 - \$5,100
  - \$5,100.01 - \$10,000
  - \$10,000.01 - \$17,000
  - \$17,000.01 - \$34,000
  - Unleased Federal Land



330 Gals B-10  
 Chemical Spill



THISTLE UNIT #71H  
 Sec 27, T23S, R33E