

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Cimarex Energy	Contact	Christine Alderman
Address	600 N Marienfeld Ste 600 Midland TX	Telephone No.	432-853-7059
Facility Name	Cascade 29-1	Facility Type	production
Surface Owner	Federal	Mineral Owner	
		API No.	30-025-40346

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	29	25S	33E	330	N	350	W	Lea

Latitude 32.10795 Longitude -103.60165

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	300 bbls	Volume Recovered	90 bbls
Source of Release	poly flowline	Date and Hour of Occurrence	06/06/2015	Date and Hour of Discovery	06/06/2015 pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Kellie Jones/Jeffery Robertson		
By Whom?	Christine Alderman	Date and Hour	06/07/2015 4:40 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By OCD District 1 at 7:11 am, Jun 30, 2015

Describe Cause of Problem and Remedial Action Taken.*

Trucking company was moving a rig down the pipeline road near location and part of the derrick sliced the polyline open.

Describe Area Affected and Cleanup Action Taken.*

fluids ran approximately 140 yards along the lease road (the trucks kept driving through it and got stuck), and then approximately 320 yards down a dry creek bed 15 feet wide at widest point. Diversified assessed the release and sampled. A work plan will developed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Christine Alderman</i>		OIL CONSERVATION DIVISION	
Printed Name: Christine Alderman		Approved by Environmental Specialist: <i>K...</i>	
Title: ESH Supervisor		Approval Date: 06/30/2015	Expiration Date: .09/30/2015
E-mail Address: calderman@cimarex.com		Conditions of Approval:	
Date: 6/26/2015 Phone: 432-853-7059		Site samples required. Delineate and remediate as per MNOCD guides. Geotag photographs of remediation required.	
		Attached <input type="checkbox"/> 215099 1RP-3701	

* Attach Additional Sheets If Necessary

nKJ1518126122
pKJ1518126317