

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Condor State #1H	Facility Type: Battery

Surface Owner: State	Mineral Owner:	API No. 30-025-40814
----------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	20	18S	35E	60	North	330	West	Lea

Latitude 32.740406 Longitude -103.4872055

NATURE OF RELEASE

Type of Release: Oil & Water	Volume of Release: 3 bbls oil ; 15 bbls PW	Volume Recovered: 1 bbls oil ; 13 bbls PW
Source of Release: Hole in Fire tube	Date and Hour of Occurrence: 6/20/2015 8:00 am	Date and Hour of Discovery: 6/20/2015 8:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By OCD District 1 at 9:22 am, Jul 15, 2015

Describe Cause of Problem and Remedial Action Taken.*

This release was caused by a hole in the fire tube of the heater treater. A vacuum truck was dispatched to recover any standing fluids.

Describe Area Affected and Cleanup Action Taken.*

This release occurred within the lined bermed area. The facility was cleaned, repaired and put back into service.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: 	
Title: Senior Environmental Coordinator	Approval Date: 07/15/2015	Expiration Date: ///
E-mail Address: atrujillo@concho.com	Conditions of Approval: Geotagged photos of remediation required.	Attached <input type="checkbox"/> ogrid 229137 IRP-3730
Date: July 4, 2015 Phone: 575-748-6940		

* Attach Additional Sheets If Necessary

nJXK1519633884

pJXK1519634124

 **CONCHO** COG Operating LLC

CONDOR STATE #1H
UNIT D, SEC. 20-T18S-R35E
60' FNL & 330' FWL
LEA COUNTY, NM
API #30-025-40814

