

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Chancey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(432) 685-5824
Facility Name	CD Woolworth Tank Battery	Facility Type	Gathering
Surface Owner	RRR Land & Cattle Co.	Mineral Owner	
		API No.	30-025-32862

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
SW ¼	30	24S	37E					Lea County, NM

Latitude N 32.18641° Longitude W 103.20506°

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	40 bbls	Volume Recovered	1 bbl
Source of Release	Leak in 2" circulating line on the discharge side between the pump and the heater treater within the fire wall	Date and Hour of Occurrence	05/04/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Geoffrey Leking, NMOCD		
By Whom?	Kathy Purvis, BBC International	Date and Hour	05/05/2014 @ 9:56 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

APPROVED

By OCD District 1 at 3:12 pm, Jul 27, 2015

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

A leak in a 2" circulating line caused 40 bbls of oil to spill onto the ground. A vacuum truck recovered 1 bbl and the line was repaired or replaced.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 100' x 20' on location within the fire wall. Remediation was completed in accordance with the remediation plan approved by Tomas Oberding of NMOCD via email on 10/22/2014.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Chancey Summers	Approved by Environmental Specialist: 	
Title: HES Lead	Approval Date: 07/27/2015	Expiration Date: //
E-mail Address: Chancey.Summers@oxy.com	Conditions of Approval: //	Attached <input type="checkbox"/> IRP-3040
Date: 7-13-15	Phone: (432) 685-5824	

* Attach Additional Sheets If Necessary

REVIEWED

By OCD District 1 at 3:11 pm, Jul 27, 2015