

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Chancey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(432) 685-5824
Facility Name	Red Tank 28 Federal #3 SWD Battery	Facility Type	Battery
Surface Owner	BLM	Mineral Owner	
		API No.	30-025-31754

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	28	22S	32E					Lea County, NM

Latitude N 32.36860° Longitude W 103.67844°

### NATURE OF RELEASE

Type of Release	Oil, produced water, and rain water	Volume of Release	50 bbls	Volume Recovered	40 bbls
Source of Release	Skimmer tank overflowed	Date and Hour of Occurrence	07/03/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Tomas Oberding- NMOCD; Sol Hughes-BLM		
By Whom?	Jennifer Gilkey, BBC International	Date and Hour	07/11/2014 @ 3:08 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

**APPROVED**

By OCD District 1 at 2:17 pm, Jul 27, 2015



Describe Cause of Problem and Remedial Action Taken.\*

A skimmer tank overflowed and spilled 50 bbls of oil, produced water, and rain water onto the ground. A vacuum truck was able to recover 40 bbls of fluid.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 30' x 200' on location. Remediation was completed in accordance with the remediation plan approved by Tomas Oberding of NMOCD via email on 01/14/2015 and approved by Sol Hughes of the BLM via email on 02/24/2015.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>		
Printed Name: Chancey Summers	Approved by Environmental Specialist: 		
Title: HES Lead	Approval Date: 07/27/2015	Expiration Date: //	
E-mail Address: Chancey_Summers@oxy.com	Conditions of Approval: //	Attached <input type="checkbox"/>	
Date: 7-13-15	Phone: (432) 685-5824	1RP-3182	

\* Attach Additional Sheets If Necessary

**REVIEWED**

By OCD District 1 at 2:17 pm, Jul 27, 2015