

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

#### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Tandem Energy Corporation	Contact	Ernie Sanchez
Address	2700 Post Oak Blvd. Ste 1000 Houston, Tx 77056	Telephone No.	575-703-6865
Facility Name	Yates Tank Battery	Facility Type	Tank Battery
Surface Owner	Mineral Owner	API No.	HOBBS OCD

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	32	21S	35E					Lea

Latitude 32° 26.569 N Longitude 103° 23.186W

#### NATURE OF RELEASE

Type of Release	Crude Oil	Volume of Release	40 bbls.	Volume Recovered	none
Source of Release	tank	Date and Hour of Occurrence		Date and Hour of Discovery	6/25/2015
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

**RECEIVED**

By OCD District 1 at 8:29 am, Jul 28, 2015

Describe Cause of Problem and Remedial Action Taken.\*



Dump valve on separator malfunctioned causing crude oil to be sent to water tank.

Describe Area Affected and Cleanup Action Taken.\*

Crude oil was spilled within tank area. The area of the spill will be remediated by removing all of the contaminated soil will be removed and properly disposed of.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

#### OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist: 		
Printed Name: Kimmy Watson			
Title: Manager, HSE and Compliance	Approval Date: 07/28/2015	Expiration Date: 09/28/2015	
E-mail Address: kimmyw@t5energy.com	Conditions of Approval: Discrete site samples required. Delineate and remediate per NMOCD guides. Geotagged photos of remediation required.		Attached <input type="checkbox"/> 1RP 3768
Date: 7/1/2015	Phone: 713-987-7320		

\* Attach Additional Sheets If Necessary

pJXK1520930467

nJXK1520930187