

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company Chevron USA Inc.	Contact Stephen Gwin
Address 15 Smith Rd, Midland, TX.	Telephone No. 575-263-0427 Cell - 575-408-0073
Facility Name Gramma Ridge CTB	Facility Type Battery
Surface Owner	Mineral Owner
API No's. 30-025-41811 30-025-41731 and 30-025-42060	

**LOCATION OF RELEASE**

Unit Letter B	Section 14	Township 24S	Range 34E	Feet from the 330	North/South Line NORTH	Feet from the 2300	East/West Line EAST	County Lea
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	---------------

Latitude 32.223755 N Longitude -103.439165 W

**NATURE OF RELEASE**

Type of Release Flare	Volume of Release 393Mcf	Volume Recovered
Source of Release Flare	Date and Hour of Occurrence 6/1/2015 - 7/31/2015	Date and Hour of Discovery 6/1/2015
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? Stephen Gwin	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

**RECEIVED**

By OCD District 1 at 2:18 pm, Aug 04, 2015

Describe Cause of Problem and Remedial Action Taken.\*

Targa is having intermittent compressor problems. This is a new well and compressor issues are being worked on by Targa. The flare is operated as a safety device.

Describe Area Affected and Cleanup Action Taken.\*

N/A

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Stephen Gwin	Approved by Environmental Specialist: 	
Title: HES Specialist	Approval Date: 08/04/2015	Expiration Date: ///
E-mail Address: Stephen.gwin@chevron.com	Conditions of Approval: ///	Attached <input type="checkbox"/>
Date: 8/1/2015 Phone: 575-263-0427	IRP 3779	

\* Attach Additional Sheets If Necessary