

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

☐ Initial Report ☒ Final Report

Name of Company Chevron USA Inc.	Contact Stephen Gwin	
Address 15 Smith Rd, Midland, TX.	Telephone No. 575-263-0427 Cell - 575-408-0073	
Facility Name Red Hill 2 Battery	Facility Type Battery	
Surface Owner	Mineral Owner	API No. 30-025-41546 and 30-025-41907

**LOCATION OF RELEASE**

Unit Letter P	Section 2	Township 25S	Range 33E	Feet from the 330	North/South Line South Line	Feet from the 340	East/West Line East Line	County Lea
------------------	--------------	-----------------	--------------	----------------------	--------------------------------	----------------------	-----------------------------	---------------

Latitude 32.153237 N Longitude 103.535237W

**NATURE OF RELEASE**

Type of Release Flare	Volume of Release 23,136 mcf	Volume Recovered
Source of Release Flare	Date and Hour of Occurrence 6/1/2015 - 7/31/2015	Date and Hour of Discovery 6/1/2015
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kellie Jones	
By Whom? Stephen Gwin	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

**RECEIVED**

By OCD District 1 at 12:46 pm, Aug 05, 2015

Describe Cause of Problem and Remedial Action Taken.\*

Flaring is due to DCP intermittent compressor issues at their Antelope Ridge Facility. The flare is operated as a safety device.



Describe Area Affected and Cleanup Action Taken.\*

N/A

**APPROVED**

By OCD District 1 at 12:46 pm, Aug 05, 2015

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>		
Printed Name: Stephen Gwin	Approved by Environmental Specialist: 		
Title: Health and Environment Specialist	Approval Date: 08/05/2015	Expiration Date: //	
E-mail Address: Stephen.gwin@chevron.com	Conditions of Approval: //	Attached <input type="checkbox"/> 241333 IRP-3783	
Date: 8/1/2015 Phone: 575-263-0427			

\* Attach Additional Sheets If Necessary

nKJ1521746515  
nKJ1521746515