

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company ARMSTRONG ENERGY CORPORATION	Contact BRUCE STUBBS	
Address P.O. BOX 1973, ROSWELL, NM 88202	Telephone No. 575-625-2222	
Facility Name GOVERNMENT "G" SWD LINE	Facility Type FLOWLINE	
Surface Owner U.S. - BLM	Mineral Owner U.S.	API No.

LOCATION OF RELEASE

Unit Letter M	Section 25	Township 19S	Range 34E	Feet from the 1000	North/South Line SOUTH	Feet from the 900	East/West Line WEST	County LEA
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	---------------

Latitude 32.62780N Longitude 103.51944W

NATURE OF RELEASE

Type of Release PRODUCED WATER AND OIL	Volume of Release 70 BW & 2 BO	Volume Recovered 15 BBLS.
Source of Release SPLIT IN FLOWLINE	Date and Hour of Occurrence 10-12-06 PM	Date and Hour of Discovery 10-12-06 8:00 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.* N/A

APPROVED

By OCD District 1 at 2:10 pm, Aug 27, 2015

Describe Cause of Problem and Remedial Action Taken.*

REPAIRED FLOWLINE. PICKED UP 15 BBLS. FLUID. THE AREA HAS BEEN TREATED WITH MICROBLAZ AND RESEEDDED. ALL BUT AN AREA APPROXIMATELY 75' X 30' HAS RECOVERED.



Describe Area Affected and Cleanup Action Taken.*

THE AREA 75' X 30' WILL BE REMEDIATED AS PER THE ATTACHED PLAN.

RECEIVED

By OCD District 1 at 2:10 pm, Aug 27, 2015

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: BRUCE STUBBS	Approved by Environmental Specialist: 		
Title: ENGINEER	Approval Date: 08/27/2015	Expiration Date: //	
E-mail Address: bastubbs@armstrongenergycorp.com	Conditions of Approval: //		Attached <input type="checkbox"/> 1RP-1088
Date: 6-8-15 Phone: 575-625-2222			

* Attach Additional Sheets If Necessary