

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	Kevin O. Butler & Associates, Inc.	Contact	Lisa Buelta
Address	P.O. Box 1171 Midland, TX 79701	Telephone No.	432-682-1178
Facility Name	South Caprock Queen	Facility Type	Injection

Surface Owner	Mineral Owner	API No.	30-005-00658
---------------	---------------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	30	15S	31E	1980	FSL	1980	FEL	LEA

Latitude 32.9852791 Longitude -103.8590851 NAD 83

NATURE OF RELEASE

Type of Release	Water	Volume of Release	15	Volume Recovered	0
Source of Release	Injection Pump	Date and Hour of Occurrence	8/9/15	Date and Hour of Discovery	8/18/15
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

APPROVED
By OCD District 1 at 8:40 am, Aug 31, 2015

Describe Cause of Problem and Remedial Action Taken.* Hole in 1 inch nipple on discharge side blew out.

RECEIVED
By OCD District 1 at 8:40 am, Aug 31, 2015

Describe Area Affected and Cleanup Action Taken.*

Affected area has been cleaned from where Salt Water had hit the ground. Contaminated dirt has been replaced with clean dirt.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Lisa Buelta</i>	OIL CONSERVATION DIVISION		
Printed Name: Lisa Buelta	Approved by Environmental Specialist:		
Title: Compliance Reporting	Approval Date: 08/31/2015	Expiration Date: //	
E-mail Address: lisab@kobutler.com	Conditions of Approval:	Attached <input type="checkbox"/>	
Date: 8/24/2015 Phone: 432-682-1178	//	1RP-3810	

* Attach Additional Sheets If Necessary