

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

☐ Initial Report ☒ Final Report

Name of Company: OXY USA	Contact: Tony Aguilar	
Address: 1017 W Stanolind Road	Telephone No.	
Facility Name: South Hobbs Grayburg San Andres Unit 136	Facility Type:	
Surface Owner:	Mineral Owner: OXY	Lease No. 30-025-28339

**LOCATION OF RELEASE**

Unit Letter C	Section 4	Township 19S	Range 38E	Feet from the	North/South Line	Feet from the	East/West Line	County
------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	--------



Latitude: 32.689630 Longitude: -103.153430

**NATURE OF RELEASE**

Type of Release: Oil and Produced water	Volume of Release: 3 BBLS OIL 697 BBLS WATER	Volume Recovered:
Source of Release: Flowline	Date and Hour of Occurrence: 8/21/2014 3:12 PM	Date and Hour of Discovery 8/21/2014
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Tomas Oberding	
By Whom? Tony Aguilar	Date and Hour: 8/21/2014	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
<div><b>APPROVED</b> By OCD District 1 at 8:42 am, Sep 04, 2015</div>		
Describe Cause of Problem and Remedial Action Taken.*		
Cause of leak internal and external Corrosion		
<div><b>RECEIVED</b> By OCD District 1 at 8:42 am, Sep 04, 2015</div>		
Describe Area Affected and Cleanup Action Taken.*		
Safety & Environmental Solutions, Inc. has remediated the spill site in accordance with NMOCD guidelines and approval.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

**OIL CONSERVATION DIVISION**

Signature: 	Approved by District Supervisor: 	
Printed Name: Tony Aguilar	Approval Date: 09/04/2015	Expiration Date: //
Title: HSE Specialist	Conditions of Approval: //	
E-mail Address: Raymond_Aguilar@oxy.com	Attached <input type="checkbox"/> <b>IRP-3478</b>	
Date: 9/3/2015 Phone: 575-390-6312		

\* Attach Additional Sheets If Necessary