

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Nadel and Gussman Permian, LLC	Contact: Bill Dougherty	
Address: 601 N. Marienfeld, Suite 508, Midland, TX 79707	Telephone No. 325-998-7107	
Facility Name: Pearsall 6 Federal #1	Facility Type: Oil Well	
Surface Owner State of NM	Mineral Owner	API No. 30-025-39487

LOCATION OF RELEASE

Unit Letter P	Section 6	Township 18 S	Range 32 E	Feet from the 660	North/South Line SOUTH	Feet from the 990	East/West Line EAST	County LEA
------------------	--------------	------------------	---------------	----------------------	---------------------------	----------------------	------------------------	---------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Oil and Water	Volume of Release ~40 BBLS	Volume Recovered 38 BBLS
Source of Release Heater Treater Fire Tube Leak	Date and Hour of Occurrence Estimated to be 12 Noon, 9/6/2015	Date and Hour of Discovery 12:30 PM 9/6/2015
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos of the BLM and Kellie Jones of the OCD	
By Whom? Bill Dougherty	Date and Hour 3:00 PM 9/7/2015	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By OCD District 1 at 1:42 pm, Sep 09, 2015

Describe Cause of Problem and Remedial Action Taken.*

A hole in the fire tube. Sucked up the oil and water on location.

Describe Area Affected and Cleanup Action Taken.*

10 BBLS of oil and water were released outside of the berm and 30 BBLS of oil and water were released inside the berm. No oil or water were released off location

Double R arrived on location at 1:00 PM. They sucked up 15 BBLS of oil and 15 BBLS of water inside the berm and 8 BBLS of oil and water outside of the berm. Double R took the 8 BBLS to the Loco Hills SWD.

Roadrunner arrived on location to clean after Double R sucked up the fluid. Roadrunner took approximately 2.5 loads = 30 cubic yards of soil to R360.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:



Printed Name: Sarah Presley

Approved by Environmental Specialist:



Title: Regulatory Analyst

Approval Date: 09/09/2015

Expiration Date: 11/09/2015

E-mail Address: spresley@naguss.com

Conditions of Approval:
Discrete site samples required. Delineate and
remediate per NMOCD guidelines.

Attached ☐
1RP 3846

Date: 9/9/2015

Phone: 432-682-4429

Geotagged photos of remediation required.
Ensure BLM Concurrence/approval.

pJXK1525249222
nJXK1525247959

* Attach Additional Sheets If Necessary