

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Bevo 11 Federal #4H Battery	Facility Type: Battery

Surface Owner: Federal	Mineral Owner:	API No. 30-025-41804
------------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	11	22S	33E	700'	South	890'	East	Lea

Latitude 32.4009247 Longitude -103.5375214

NATURE OF RELEASE

Type of Release: Oil & Produced Water	Volume of Release: 20 bbls Oil; 30 bbls PW	Volume Recovered: 15 bbls Oil; 25 bbls PW
Source of Release: Gasket Failure	Date and Hour of Occurrence: 8/21/2015 10:50 pm	Date and Hour of Discovery: 8/21/2015 10:50 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kellie Jones – NMOCD / Jim Amos – BLM	
By Whom? Amanda Trujillo	Date and Hour: Mon 8/24/2015 6:23 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED
By OCD District 1 at 7:52 am, Sep 16, 2015

Describe Cause of Problem and Remedial Action Taken.*

This release was caused by a gasket failure on a heater treater. Vacuum trucks were dispatched to recover all standing fluid. Microblaze was applied to the area impacted outside the containment.

Describe Area Affected and Cleanup Action Taken.*

This release was mostly contained with the lined containment of the facility. A spray misted the pasture. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: 	
Title: Senior Environmental Coordinator	Approval Date: 09/16/2015	Expiration Date: 11/16/2015
E-mail Address: atrujillo@concho.com	Conditions of Approval:	
Date: 9/4/2015 Phone: 575-748-6940	Discrete site samples required. Delineate and remediate per NMOCD guidelines.	Attached <input type="checkbox"/> IRP 3856
	Geotagged photos of remediation required.	nJXK1525928160
	Ensure BLM concurrence/approval.	pJXK1525928271

* Attach Additional Sheets If Necessary