

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company Cimarex Energy	Contact Christine Alderman
Address 600 N Marienfeld Ste 600 Midland TX	Telephone No. 432-853-7059
Facility Name Chief 30 State #1	Facility Type Production

Surface Owner	Mineral Owner	API No. 30-025-40406
---------------	---------------	----------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	30	20S	35E	660	S	330	W	Lea

Latitude 32.538753 Longitude -103.504077

**NATURE OF RELEASE**

Type of Release Produced Water	Volume of Release 65 bbls	Volume Recovered 40 bbls
Source of Release poly flowline	Date and Hour of Occurrence 09/24/15	Date and Hour of Discovery 09/24/15
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kellie Jones	
By Whom? Christine Alderman	Date and Hour 9/25/15 10:30 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

**RECEIVED**  
By JKeyes at 1:51 pm, Sep 25, 2015

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
A poly flowline over pressured due to the line plugging up coming from the well.

Describe Area Affected and Cleanup Action Taken.\*  
Location pad and grazing land were impacted. Our consultant will assess and delineate. A work plan will be developed and submitted.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Christine Alderman</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Christine Alderman	Approved by Environmental Specialist: <i>Jan Keyes</i>	
Title: ESH Supervisor	Approval Date: 09/25/2015	Expiration Date: 11/25/2015
E-mail Address: calderman@cimarex.com	Conditions of Approval: Discrete site samples required. Delineate and remediate per NMOCD guidelines. Geotagged photos required.	Attached <input type="checkbox"/> 1RP 3888
Date: 9/25/15 Phone: 432-853-7059		

\* Attach Additional Sheets If Necessary

pJXK1526849808  
nJXK1526849729