MDistrict I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

Name of Company: Chevron USA Inc.

* Attach Additional Sheets If Necessary

Address: 15 Smith Rd., Midland, TX, 79705

State of New Mexico **Energy Minerals and Natural Resources**

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Form C-141

Final Report

Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Cell: 985-502-2342

Release Notification and Corrective Action

OPERATOR

Contact: Nick Hampton

Telephone No.: Work: 575-704-3143

Facility Name: Vacuum Giorietta West Unit Battery Facility Type: Battery									
Surface Own	er: N/A			Mineral Own	ner: State of New	Mexico	API No.:		
LOCATION OF RELEASE									
Unit Letter B	Section 1	Township 18S	Range 34E	Feet from the	North/South Line	Feet from the	East/West Li	ne County Lea	
Latitude = 32.796051 Longitude = -103.514502									
2000000									
NATURE OF RELEASE									
Type of Releas	e: Flare				Volume of Rel	Volume of Release: 114 MCF Volume Recovered: 0 MCF			
Source of Release: Flare						Date and Hour of Occurrence:Date and Hour of Discovery:10/07/2015 03:00PM10/07/2015 03:00PM			
Was Immediate Notice Given? ☐ Yes ☐ No ☒ Not Required						If YES, To Whom?			
By Whom?					Date and Hou	Date and Hour:			
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse:			
☐ Yes ⊠ No									
If a Watercourse was Impacted, Describe Fully.*									
RECEIVED									
By JKeyes at 9:37 am, Oct 13, 2015									
Describe Cause of Problem and Remedial Action Taken.*									
Flaring at the VGWU Battery due to the compressor going down on high discharge. Operations troubleshot, repaired and restarted the compressor.									
Compressor									
Describe Area Affected and Cleanup Action Taken.*									
N/A									
								ant to NMOCD rules and	
								ses which may endanger ve the operator of liability	
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other									
federal, state, or local laws and/or regulations.									
					9	OIL CONSERVATION DIVISION			
Signature: Nick Hampton									
					Approved by En	Approved by Environmental Specialist:			
Printed Name: Nick Hampton									
Title: HE Specialist					Approval Date:	Approval Date: Expiration Date: ///		Date: ///	
E-mail Address: cikb@chevron.com Date: 10/10/2015				Conditions of Ar	Conditions of Approval:				
					///		Attached \(\text{TRP 3910} \)		