

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

XX Initial Report Final Report

Name of Company: Grand Banks Energy	Contact: Wayne Price-Price LLC
Address: 10 Desta Drive Midland TX 79705	Telephone No. 505-715-2809
Facility Name: ARU #14	Facility Type: Oil Flow Line

Surface Owner: NMSLO	Mineral Owner: NMSLO	API No.30-025-00365
----------------------	----------------------	---------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	2	16S	32E	20	South	660	East	Lea

Latitude N 32 56 36.29 Longitude W 103 43 51.34

NATURE OF RELEASE- See Initial Report Attached

Type of Release: Crude Oil	Volume of Release: 75 bbl-estimated-initially	Volume Recovered- Pending
Source of Release: New Surface Poly Flow Line	Date and Hour of Occurrence: Sometime Thursday Night-Fri Morning Oct 29-30?	Date and Hour of Discovery: Friday Oct 30, 2015 9 am estimated
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? NA	
By Whom? Pumper	Date and Hour Same as Above	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

REVIEWED

By Kellie Jones at 1:29 pm, Nov 19, 2015

If a Watercourse was Impacted, Describe Fully.*- **NO**

Describe Cause of Problem and Remedial Action Taken. Appears new poly flow line parted in new welded joint located on surface just past road crossing of Patterson oil field lease road, north side. System shut down and emergency crews called out, made 1-811 call and started emergency response actions to stop flow of oil.

Describe Area Affected and Cleanup Action Taken. Approximately 600' x 75' surface pasture land impacted. Emergency response actions to date, scraped up all saturated oily soil and hauled approximately 400 yards to Gandy-Marley Landfill. Non-saturated remaining soils being scraped up and stocked piled for evaluation, installed runoff berms. Once Emergency actions are complete, Grand Banks will perform vertical and horizontal investigations to determine a path forward for final closure.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Approved by Environmental Specialist:




Signature:

Printed Name: Wayne Price-Agent/Consultant for Grand Banks

Title: Price LLC-Mg Member

Approval Date: **11/19/2015**

Expiration Date: **01/19/2016**

E-mail Address: wayneprice77@earthlink.net

Conditions of Approval:
Site samples required. Delineate and remediate as per MNOCD guides. Geotag photographs of remediation required.

Attached
1RP-3985

Date: Nov 02, 2015 Phone: 505-715-2809

* Attach Additional Sheets If Necessary-

**nKJ1532349151
pKJ1532349292**