

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**RECEIVED**

By JKeyes at 1:26 pm, Dec 11, 2015

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: <b>Devon Energy Production Co LP (6137)</b>	Contact: <b>Jeff Heath, Devon Completions Asst. Foreman</b>
Address: <b>PO Box 250 Artesia, NM 88211</b>	Telephone No. <b>575- 513-2274</b>
Facility Name: <b>Black Mamba 15 State Com 8H</b>	Facility Type : <b>Well location associated with spill #2 (south)</b>

Surface Owner at spill: <b>State</b>	Mineral Owner at spill: <b>Federal</b>	API No. <b>30-025-42630</b>
--------------------------------------	----------------------------------------	-----------------------------

### LOCATION OF RELEASE

Unit Letter <b>D</b>	Section <b>11</b>	Township <b>23S</b>	Range <b>33E</b>	Feet from the <b>74</b>	North/South Line <b>North</b>	Feet from the <b>322</b>	East/West Line <b>West</b>	County <b>Lea</b>
-------------------------	----------------------	------------------------	---------------------	----------------------------	----------------------------------	-----------------------------	-------------------------------	----------------------

Latitude: **32.326320** Longitude: **-103.550600**

### NATURE OF RELEASE

Type of Release: <b>Produced Water</b>	Volume of Release: <b>10 bbls</b>	Volume Recovered: <b>2 bbls</b>
Source of Release: <b>Water transfer pump</b>	Date and Hour of Occurrence <b>12/8/2015; 5:20 PM</b>	Date and Hour of Discovery <b>12/8/2015; 5:20 PM</b>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>OCD-Kellie Jones</b>	
By Whom? <b>Jeff Heath, Devon Asst. Completions Foreman</b>	Date and Hour: <b>OCD: 12/8/2015; 7:45 PM</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. <b>NA</b>	

If a Watercourse was Impacted, Describe Fully.\* **NA**



Describe Cause of Problem and Remedial Action Taken.\*

A mobile water transfer pump in operation broke apart on the backend causing a produced water spill. The valves were immediately shut off and the transfer line clamp was attached to prevent further release.

Describe Area Affected and Cleanup Action Taken.\*

A spill of 10 barrels of produced water occurred approximately ¾ of a mile north of the Black Mamba 15 State Com 8H location off of the lease road into the pasture. The spill area affected is approximately 14,000 square feet in various directions on to pipeline easement and pasture. A vacuum truck was called and was able to recover 2 barrels of the water. An environmental company has been called to test and create a remediation plan for submittal.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Denise Menoud</b>	Approved by Environmental Specialist: 	
Title: <b>Field Admin Support</b>	Approval Date: <b>12/11/2015</b>	Expiration Date: <b>02/11/2016</b>
E-mail Address: <b>Denise.Menoud@dvn.com</b>	Conditions of Approval: <b>Discrete site samples required. Delineate and remediate per NMOCD guidelines.</b>	Attached <input type="checkbox"/> <b>1RP 4012</b>
Date: <b>12/9/2015</b>	Phone: <b>575-746-5544</b>	

\* Attach Additional Sheets If Necessary

nJXK1534548184  
pJXK1534548280



Spill 12/8/15 Blk Mamba



This map is for illustrative purposes only and is not intended to be used for legal or regulatory purposes. It is not a warranty, representation, or guarantee of any kind regarding the map.

WGS\_1984\_Web\_Mercator\_Auxiliary\_Sphere  
Prepared by: D Menoud  
Map is current as of: 09-Dec-2015





