

RECEIVED**By JKeyes at 12:45 pm, Dec 21, 2015**

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: XTO Energy, Inc	Contact: Stephanie Rabadue
Address: 500 W. Illinois St Ste 100 Midland, Texas 79701	Telephone No.: 432-620-6714
Facility Name: Perla Negra Federal Com #4H	Facility Type: Well Site

Surface Owner: Bureau of Land Management	Mineral Owner: Bureau of Land Management	API No.: 30-025-42577
--	--	-----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	25	19S	34E	298	North	485	East	Lea

Latitude: 32.637653 N Longitude: 103.506267 W

NATURE OF RELEASE

Type of Release: Blow Out	Volume of Release: 301.3bbls oil 192.8mcf gas	Volume Recovered: 158.63bbls (to date) Clean-Up in Progress
Source of Release: Well	Date and Hour of Occurrence 12/1/2015, 11AM CST	Date and Hour of Discovery 12/1/2015, 11AM CST
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos, Bureau of Land Management	
By Whom? Bo Jackson, XTO Energy	Date and Hour: 12/1/2015 2:30pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. Not Applicable	

If a Watercourse was Impacted, Describe Fully.*
Not Applicable. No watercourse in vicinity.

Describe Cause of Problem and Remedial Action Taken.*

Pulling unit was fishing parted swab line and cups, they pulled out tubing until got to the tail of the swab line. Installed a TIW valve and latched on with rod elevator and pulled out hole. Tied onto the tubing to pump down and it was plugged. Took off the TIW and started out of the hole when well kicked. Wild well control came to location and well was secured by placing TIW valve on the well head.

Describe Area Affected and Cleanup Action Taken.*

Estimated area affected to be 500'x500'.
XTO Energy, Inc has hired a third-party environmental company to evaluate and perform clean-up. Clean-up is in progress. .

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Stephanie Rabadue</i>	OIL CONSERVATION DIVISION	
Printed Name: Stephanie Rabadue	Approved by Environmental Specialist: <i>Jane Keyes</i>	
Title: Regulatory Analyst	Approval Date: 12/21/2015	Expiration Date: 02/21/2016
E-mail Address: stephanie_rabadue@xtoenergy.com	Conditions of Approval: Discrete site samples required. Delineate and remediate per NMOCD guidelines.	Attached <input type="checkbox"/> 1RP 4049
Date: 12/21/2015 Phone: 432-620-6714	Geotagged photos recommended. Ensure BLM concurrence/approval.	n\XK1535545760 p\XK1535545828

* Attach Additional Sheets If Necessary