

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
By JKeyes at 1:12 pm, Dec 31, 2015
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	Devon Energy Production	Contact	Rudy Zuniga, Production Foreman
Address	6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No.	575-390-5435
Facility Name	Great Bear Park 24 Fed 1	Facility Type	Oil
Surface Owner	Federal	Mineral Owner	Federal
		API No.	30-025-39206

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	24	18S	33E	1680	FNL	1980	FEL	Eddy

Latitude: 32.73569000

Longitude: 103.6140000

NATURE OF RELEASE

Type of Release Produced Water spill	Volume of Release 30bbbls	Volume Recovered 30bbbls
Source of Release Main water line	Date and Hour of Occurrence December 18, 2015 8:40 AM	Date and Hour of Discovery December 18, 2015 8:40 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos, BLM Kelly Jones, OCD	
By Whom? Rudy Zuniga, Production Foreman	Date and Hour Jim Amos, BLM December 18, 2015 2:00 PM Kelly Jones, OCD December 18, 2015 2:05 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Main water line had corrosion along the bottom and side of line causing a 30bbl produced water release into lined containment. The valves from the heater treater and the transfer pump were immediately closed to stop the release.		
Describe Area Affected and Cleanup Action Taken.* All 30bbl of produced water were contained in lined containment and a vac truck was called to clean up containment. All 30bbbls produced water were recovered and the containment was checked for holes with none found.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <i>Sheila Fisher</i>	OIL CONSERVATION DIVISION	
Printed Name: Sheila Fisher	Approved by Environmental Specialist: <i>Jam Keyes</i>	
Title: Field Admin Support	Approval Date: 12/31/2015	Expiration Date: ///
E-mail Address: Sheila.Fisher@dvn.com	Conditions of Approval: ///	Attached <input type="checkbox"/> 1RP 4060
Date: 12/22/15	Phone: 575.748.1829	

* Attach Additional Sheets If Necessary

nJXK1536547358
pJXK1536547471

Great Bear Park 24 Fed 1

30bbl produced water release



This map is for illustrative purposes only and is neither a legally recorded map nor survey and is not intended to be used as one. Devon makes no warranty, representation, or guarantee of any kind regarding this map.

WGS_1984_Web_Mercator_Auxiliary_Sphere
Prepared by: Sheila Fisher
Map is current as of: 21-Dec-2015



Miles
0 0.01 0.02 0.04 1:1,779





