

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

#### OPERATOR

☒ Initial Report ☒ Final Report

Name of Company: Targa Midstream Services	Contact: Bill Little	*This will be treated as just an initial report. KJ
Address PO Box: 1909 Eunice, NM 88231	Telephone No.: 575.631.7099	
Facility Name: 3 miles south of Eunice, Middle Plant	Facility Type: 12" lateral gathering line	

Surface Owner: Mr. Hughes	Mineral Owner	API No.
---------------------------	---------------	---------

#### LOCATION OF RELEASE

Unit Letter	Section 15	Township 22S	Range 37E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
-------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude 32.3985.34 Longitude 103.159.328

#### NATURE OF RELEASE

Type of Release: Natural Gas and liquid	Volume of Release: 1000 MCF of natural gas by calculation 40 BBLS of liquid	Volume Recovered: None
Source of Release: 3 <sup>rd</sup> party transport struck Targa's 12" pipeline valve	Date and Hour of Occurrence: 12/11/15, 10:00 PM	Date and Hour of Discovery: 12/11/2015, 11:30 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mr. Maxie Brown, Hobbs Office	
By Whom? Cindy Klein	Date and Hour: 03:45 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

**REVIEWED**

**By Kellie Jones at 3:33 pm, Jan 06, 2016**



Describe Cause of Problem and Remedial Action Taken.\*

Third party trucking company ran the stop sign at the intersection of Delaware Basin and Hwy. 207 then continued on, striking Targa's 12" valve which was tied into Targa's 16" main gathering line, causing a release of raw natural gas and pipeline liquid. The pipeline gathering system was isolated and depressured.

Describe Area Affected and Cleanup Action Taken.\*

The affected area has been excavated, sampled, and contaminated soil removed to a local area landfill. Targa is waiting on sample results to close the cleanup.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Bill Little	Approved by Environmental Specialist: 	
Title: Area Manager	Approval Date: 01/06/2016	Expiration Date: 03/06/2016
E-mail Address: blittle@targaresources.com	Conditions of Approval: Site samples required. Delineate and remediate as per MNOCD guides. Geotag photographs of remediation recommended.	Attached <input type="checkbox"/> 1RP-4078
Date: 12-21-15 Phone: 575.631.7099		

\* Attach Additional Sheets If Necessary

nKJ1600656867  
pKJ1600657163