

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

APPROVED

By Kellie Jones at 11:58 am, Jan 14, 2016

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Chancey Summers
Address	1017 W. Stanolind Road; Hobbs, NM 88240	Telephone No.	575-397-8216
Facility Name	South Hobbs Injection Header #3	Facility Type	Water Injection Site
Surface Owner	Oxy	Mineral Owner	
		Lease No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	10	19S	38E					Lea County, NM

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	1000 bbls of water	Volume Recovered	840 bbls
Source of Release	Hole in 8" steel injection trunk line	Date and Hour of Occurrence	9/13/2012 @ 4:00 am	Date and Hour of Discovery	09/13/2012
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Geoffrey Leking- OCD			
By Whom?	Chancey Summers	Date and Hour 09/14/2012 @ 8:17 a.m.			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

REVIEWED

By Kellie Jones at 11:58 am, Jan 14, 2016



Describe Cause of Problem and Remedial Action Taken.*

A hole in a 8" steel injection trunk line caused 1000 bbls of water to leak onto the ground. 840 bbls of water were recovered via vacuum truck. The line was repaired.

Describe Area Affected and Cleanup Action Taken.*

The area affected was approximately 400' x 200'. Remediation was performed in accordance with the remediation plan approved by Geoffrey Leking of NMOCD on 11/30/2012.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Chancey Summers		Approved by District Supervisor: 	
Title: HES Specialist		Approval Date: 01/04/2016	Expiration Date: //
E-mail Address: chancey_summers@oxy.com		Conditions of Approval: //	Attached <input type="checkbox"/> 1RP-4109
Date: 12/19/12	Phone: (575)397-8216		

* Attach Additional Sheets If Necessary

pKJ1601443568
nKJ1601443446