

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Key Energy Services	Contact	Bobby J. Sisson
Address	Box 99 Eunice N.M.	Telephone No.	806-401-4349
Facility Name	Merit Energy Silver Oak Tank Bty	Facility Type	Tank Battery
Surface Owner	Tim Carlin	Mineral Owner	State of New Mexico
		API No.	30-025-38642

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	6	19s	35E	660	North	1980	East	Lea

Latitude 32.69515 Longitude -103.49458

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	20 bbls	Volume Recovered	15 bbls
Source of Release	Transport Truck	Date and Hour of Occurrence	9:30AM 10-6-2012	Date and Hour of Discovery	Same
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour 10-6-2012 @ 9:30 AM				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
<div>REVIEWED By Kellie Jones at 8:59 am, Jan 26, 2016</div>					

Describe Cause of Problem and Remedial Action Taken.*

Transport truck left back valve open on trailer & pumped about 20 bbls of Produced Water on ground. He then proceeded to vacuum up 15 bbls of the spill. Contacted Chris Flores with Merit Energy who notified Mr. Tim Carlin of the situation. Soil remediation conducted including excavation and hauling off contaminated material. Samples taken to prove soil meets OCD criteria.

APPROVED

By Kellie Jones at 8:59 am, Jan 26, 2016

Describe Area Affected and Cleanup Action Taken.* Some of the water escaped off the pad down the Southeast corner into the pasture for about 160'. Soil remediation was conducted. Two rounds of samples were taken. First round was 16 samples on 12/05/2012. Second round was taken of 12 samples when soil remediation was completed on 01/24/2013. The sample analysis for this site shows below the action level for contaminants. Lab analysis and site photos were filed to the state as support information.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Ana Ramirez</i>		OIL CONSERVATION DIVISION	
Printed Name: Ana Ramirez		Approved by Environmental Specialist: <i>Kellie Jones</i>	
Title: Environmental Specialist Key Energy Services		Approval Date: 01/26/2016	Expiration Date: //
E-mail Address: aramirez01@keyenergy.com		Conditions of Approval: //	Attached <input type="checkbox"/> 1RP-2869
Date: 01/25/2016 Phone: 432-571-7203			

* Attach Additional Sheets If Necessary