

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

APPROVED

By Kellie Jones at 8:31 am, Jan 26, 2016

Revised August 6, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Mewbourne Oil Company	Contact: Zack Thomas	
Address: PO Box 5270 Hobbs NM 88241	Telephone No. 575-393-5905	
Facility Name: Bone Springs Central Water Flood Facility	Facility Type: Water Flood Injection Facility	
Surface Owner: BLM	Mineral Owner: BLM	API No.

LOCATION OF RELEASE

Unit Letter N	Section 23	Township 18S	Range 32E	Feet from the 660'	North/South Line South	Feet from the 1980'	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	------------------------	------------------------	----------------

Latitude 32.7275472 Longitude -103.7389861

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: estimated 297 bbls	Volume Recovered: 275 bbls PW
Source of Release: Fiberglass water tanks	Date and Hour of Occurrence 7-20-15	Date and Hour of Discovery 7-20-15 4:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kellie Jones (NMOCD) Jim Amos (BLM)	
By Whom? Zack Thomas	Date and Hour 7-21-15 10:00 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By Kellie Jones at 8:31 am, Jan 26, 2016



Describe Cause of Problem and Remedial Action Taken.*

The water flood facility was struck by lightning. Upon being struck, the facility caught fire. Maljimar VFD was immediately contacted to extinguish the fire and vacuum trucks were used to recover all standing fluid as soon as the location was deemed safe.

Describe Area Affected and Cleanup Action Taken.*

Affected area- The produced water leaked over the secondary containment behind location toward the North (100 ft by 40 ft) and Northwest (18 ft by 125 ft). Vacuum trucks recovered 225 bbls from the secondary containment and 50 bbls from pasture area. For complete details of remediation reference closure report dated January 25, 2016. Final remediation was conducted in accordance with the NMOCD's Guidelines for Remediation of Spills, Leaks and Releases.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Zack Thomas		Approved by Environmental Specialist: 	
Title: Environmental Rep.		Approval Date: 01/26/2016	Expiration Date: //
E-mail Address: zthomas@mewbourne.com		Conditions of Approval: //	Attached <input type="checkbox"/> 1RP-3748
Date: 1-25-16 Phone: 575-602-2188			

* Attach Additional Sheets If Necessary