

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	<i>Enterprise Field Services LLC</i>	Contact	<i>Alena Polk</i>
	<i>PO Box 4324, Houston, TX 77210</i>	Telephone No.	<i>575-706-4926</i>
Facility Name	<i>Pipeline ROW, Line 1009</i>	Facility Type:	<i>Gas Gathering Pipeline</i>
Surface Owner	<i>State of New Mexico</i>	Mineral Owner	<i>NA - Pipeline</i>
		Lease No.	<i>NA</i>

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<i>F</i>	<i>13</i>	<i>21S</i>	<i>34E</i>	<i>462</i>	<i>South</i>	<i>493</i>	<i>East</i>	<i>Lea</i>

Latitude: 32.480269 Longitude: W-103.425138

NATURE OF RELEASE

Type of Release	<i>Natural Gas and pipeline liquids</i>	Volume of Release:	<i>1724 MCF gas and 60 bbls liquids</i>	Volume Recovered:	<i>N/A</i>
Source of Release	<i>Pipeline Leak.</i>	Date and Hour of Occurrence	<i>1/19/2016 @ 08:45 MST</i>	Date and Hour of Discovery	<i>1/19/2016 @ 08:45 MST</i>
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	<i>Region 1 - Kellie Jones</i>		
By Whom?	<i>Alena Polk</i>	Date and Hour	<i>1/19/2016 @ 11 am</i>		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

RECEIVED

By Kellie Jones at 12:22 pm, Jan 29, 2016

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Pipeline leak was detected by a third party. Pipeline segment and free fluids were isolated, blown down, repaired following standard one-call. About 60 bbls of liquid noted on ROW.

Describe Area Affected and Cleanup Action Taken.*

A liquid spill of about 60bbls occurred as part of the leak. Remediation actions will follow the Enterprise Products, General Release Notification, Response and Remediation Plan (March 9, 2015).

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<i>Jon Fields</i>		
Printed Name:	<i>Jon E. Fields</i>		
Title:	<i>Director, Field Environmental</i>		
E-mail Address:	<i>jefields@eprod.com</i>		
Date:	<i>1-27-2016</i>	Phone:	<i>713-381-6684</i>
Approved by District Supervisor:		<i>Kent</i>	
Approval Date:		<i>01/29/2016</i>	Expiration Date:
Conditions of Approval:		<i>03/29/2016</i>	
Site samples required. Delineate and remediate as per NMOCD guides. Geotag photographs of remediation recommended.		Attached <input type="checkbox"/> 1RP-4121	

* Attach Additional Sheets If Necessary

nKJ1602948451
pKJ1602948741