

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

By JKeyes at 7:41 am, Mar 02, 2016

Form C-141

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	Cimarex Energy	Contact	Christine Alderman
Address	600 N Marienfeld Ste 600 Midland TX	Telephone No.	432-853-7059
Facility Name	Cascade 29 Fed 3 Battery	Facility Type	production
Surface Owner	Fed	Mineral Owner	
		API No.	30-025-41241

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	29	25S	33E	330	N	2310	E	Lea

Latitude 32.10794 Longitude -103.59317

NATURE OF RELEASE

Type of Release	produced water	Volume of Release	40 bbls	Volume Recovered	40 bbls
Source of Release	3" coated steel piping	Date and Hour of Occurrence	2/28/2016	Date and Hour of Discovery	2/28/2016
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Jaime Keyes / Jim Amos		
By Whom?	Christine Alderman	Date and Hour	2/29/2016		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.* A 3" water transfer pipe ruptured due to corrosion.					
Describe Area Affected and Cleanup Action Taken.* All fluids were recovered from a LINED berm.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature: <i>Christine Alderman</i>		OIL CONSERVATION DIVISION			
Printed Name: Christine Alderman		Approved by Environmental Specialist: <i>Jaime Keyes</i>			
Title: ESH Supervisor		Approval Date: 03/02/2016		Expiration Date: ///	
E-mail Address: calderman@cimarex.com		Conditions of Approval: ///		Attached <input type="checkbox"/>	
Date: 2/29/2016 Phone: 432-853-7059					

* Attach Additional Sheets If Necessary

nJXK1606227470
pJXK1606227546