

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**RECEIVED**  
By JKeyes at 8:53 am, Apr 15, 2016  
Form C-141  
8/2011  
Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**  Initial Report  Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: PAN HEAD FEE #021H	Facility Type: Battery

Surface Owner:	Mineral Owner: Fee	API No. 30-025-40886
----------------	--------------------	----------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	11	17S	32E	330	North	330	West	Lea

Latitude 32.8554306 Longitude -103.7446976

**NATURE OF RELEASE**

Type of Release: Oil	Volume of Release: 25 bbls	Volume Recovered: 24 bbls
Source of Release: Wellhead	Date and Hour of Occurrence: 4/3/2016 9:00 am	Date and Hour of Discovery: 4/3/2016 9:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? Jaime Keyes - NMOCD	
By Whom? Robert Grubbs Jr.	Date and Hour: 4/4/2016 6:55 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*


Describe Cause of Problem and Remedial Action Taken.\*

This release was caused by a broken chemical line the pumping tee off the wellhead. Vacuum trucks were dispatched to recover standing fluid.

Describe Area Affected and Cleanup Action Taken.\*

This release occurred at the wellhead and stayed on location. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
	Approved by Environmental Specialist: 	
Printed Name: Robert Grubbs Jr.	Approval Date: 04/15/2016	Expiration Date: 06/15/2016
Title: Senior Environmental Coordinator	Conditions of Approval:	
E-mail Address: rgrubbs@concho.com	Discrete site samples only. Delineate and remediate per NMOCD guidelines.	Attached <input type="checkbox"/> 1RP 4249
Date: April 14, 2016	Phone: 432-683-7443	

\* Attach Additional Sheets If Necessary

nJXK1610631827  
pJXK1610631964