

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**RECEIVED**

By JKeyes at 10:20 am, May 12, 2016

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: <b>ConocoPhillips</b>	Contact: <b>Jose A Zepeda</b>	
Address: <b>29 Vacuum Complex Lane</b>	Telephone No. <b>575-391-3165</b>	
Facility Name: <b>EVGSAU Sat 1</b>	Facility Type: <b>Trunk Line</b>	
Surface Owner:	Mineral Owner: N/A	API No. 30-025-26577

### LOCATION OF RELEASE

Unit Letter G	Section 29	Township 17S	Range 35E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

### NATURE OF RELEASE

Type of Release: <b>Produce Water</b>	Volume of Release: 5.39	Volume Recovered: 0
Source of Release: <b>Flow Line</b>	Date and Hour of Occurrence <b>05/11/2016 0730</b>	Date and Hour of Discovery <b>SAME</b>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jamie Keyes	
By Whom? <b>Jose A Zepeda</b>	Date and Hour: <b>05/11/16 1400 via email</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*


N/A

Describe Cause of Problem and Remedial Action Taken.\*

On May 11, 2016 at 0730 MDT at EVGSAU Sat 1, a leak was found on a discharge trunk line that resulted in a release of 5.39 bbls of produced water with 0 bbls recovered. Immediate action was to shut down the facility and notify supervisor.

Describe Area Affected and Cleanup Action Taken.\*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <b>JOSE A ZEPEDA</b>		OIL CONSERVATION DIVISION Approved by Environmental Specialist: 	
Printed Name: Jose A Zepeda			
Title: LEAD HSE	Approval Date: <b>05/12/2016</b>	Expiration Date: <b>07/12/2016</b>	
E-mail Address: <b>Jose. A. Zepeda@conocophillips.com</b>	Conditions of Approval: <b>Discrete samples only. Delineate and remediate per NMOCD guidelines.</b>		Attached <input type="checkbox"/> <b>IRP 4274</b>
Date: 05/11/2016	Phone: 575-391-3165		

\* Attach Additional Sheets If Necessary

nJXK1613337088  
pJXK1613337180