

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
By JKeyes at 7:51 am, May 19, 2016
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443
Facility Name: AIRSTRIP FEE COM #001H	Facility Type: Battery

Surface Owner: Fee	Mineral Owner: Federal	API No. 30-025-41152
--------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	07	19S	35E	190'	South	460'	East	Lea

Latitude 32.6684113 Longitude -103.4896698

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 13 bbls	Volume Recovered: 10 bbls
Source of Release: Flowline	Date and Hour of Occurrence: 5/8/2016 4:30 pm	Date and Hour of Discovery: 5/8/2016 4:30 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

This release was caused when a construction crew installing a new flowline cut into the SWD line. A vacuum truck was dispatched to recover all standing fluid.

Describe Area Affected and Cleanup Action Taken.*

This release occurred within the containment and on the backside of the battery. This release did not impact the pasture but remained on location. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Amanda T. Davis</i>	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo Davis	Approved by Environmental Specialist: <i>Jane Keyes</i>	
Title: Senior Environmental Coordinator	Approval Date: 05/19/2016	Expiration Date: 07/19/2016
E-mail Address: atrujillo@concho.com	Conditions of Approval: Discrete samples only. Delineate and remediate per NMOCD guidelines.	Attached <input type="checkbox"/> IRP 4287
Date: May 18, 2016 Phone: 575-748-6940		

* Attach Additional Sheets If Necessary

nJXK1614028144
pJXK1614028216