

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

**RECEIVED**

By JKeyes at 7:43 am, Jun 09, 2016

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company	Pyote Water Systems, LLC	Contact	Jerry Burton
Address	400 W Illinois Ste 900 MIDLAND TX 79701	Telephone No.	432-448-4917
Facility Name	Kaiser Swd	Facility Type	production Water

Surface Owner	STATE	Mineral Owner	STATE	API No.	30-025-02538
---------------	-------	---------------	-------	---------	--------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	13	21s	<del>24s</del> 34E					LEA COUNTY

Latitude 32.4808578- Longitude 103.4256592 nad 83

**NATURE OF RELEASE**

Type of Release	lightning struck load tanks while driver was unloading	Volume of Release	1050 BBLS	Volume Recovered	1050 bbls
Source of Release	production water	Date and Hour of Occurrence	5-17-16	Date and Hour of Discovery	4 PM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? JERRY BURTON via telephone by driver			
By Whom?	UNKNOWN DRIVER	Date and Hour	5/17/16 4PM		
Was a Watercourse Reached?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse. 1050 BLS			

If a Watercourse was Impacted, Describe Fully.\*

fire melted parts of the liner, water got under the liner

Describe Cause of Problem and Remedial Action Taken.\*

lightning hit load tanks and burned 6 500 bbl tanks less than 2 bbls breeched containment. called vac truck out to empty containment after the fire dept put out the fire .

Describe Area Affected and Cleanup Action Taken.\*

load side containment have clean up crew cleaning up and disposing of old tanks and cat walk to sundown

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jerry Burton</i>	<b>OIL CONSERVATION DIVISION</b>		
Printed Name: Jerry Burton	Approved by Environmental Specialist: <i>Jerry Burton</i>		
Title: NM Operations Mgr	Approval Date: 06/09/2016	Expiration Date: 08/09/2016	
E-mail Address: jerry@pyotewatersystems.com	Conditions of Approval: Discrete samples only. Delineate and remediate per NMOCD guidelines.		Attached <input type="checkbox"/> 1RP 4305
Date: 5-18-2016	Phone: 4324484917		

\* Attach Additional Sheets If Necessary

nJXK1616127644  
pJXK1616127747