

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**RECEIVED**

By JKeyes at 7:47 am, Jun 27, 2016

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report



Name of Company	Oxy Permian	Contact	Tony Aguilar
Address	1017 W. Stanolind Road	Telephone No.	(575) 397-8251
Facility Name	NHU Satellite #32 W Trunk line	Facility Type	Satellite
Surface Owner	Oxy	Mineral Owner	
		API No.	30-025-23035

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	29	18S	38E					Lea County, NM

Latitude N 32.71806° Longitude W 103.17622°

### NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	0.5 bbl oil, 30 bbls produced water	Volume Recovered	15 bbls produced water
Source of Release	Stress/fatigue of 8" fiberglass trunkline	Date and Hour of Occurrence	06/13/2016	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Maxey Brown-NMOCD		
By Whom?	Tony Aguilar/Mark Bowman- Oxy	Date and Hour	06/13/2016 @ 9:58 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
Stress/fatigue of an 8" fiberglass trunkline caused a leak of 0.5 bbl of oil and 30 bbls of produced water. A vacuum truck recovered 15 bbls of produced water and the line was repaired.					
Describe Area Affected and Cleanup Action Taken.*					
The area affected is approximately 145' x 195' both on and off location. Remediation will be completed in accordance with a remediation plan approved by NMOCD.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature: 		OIL CONSERVATION DIVISION			
Printed Name: Tony Aguilar		Approved by Environmental Specialist: 			
Title: HES Specialist		Approval Date: 06/27/2016		Expiration Date: 08/27/2016	
E-mail Address: Raymond_aguilar@oxy.com		Conditions of Approval:			
Date: 6-22-16 Phone: (575) 397-8251		Discrete samples only. Delineate and remediate per NMOCD guidelines.		Attached <input type="checkbox"/> IRP 4319	

\* Attach Additional Sheets If Necessary

nJXK1617927873  
pJXK1617927974