

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**RECEIVED**

By JKeyes at 8:42 am, Jun 27, 2016

Form C-141

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Chevron USA	Contact: Josepha DeLeon	
Address: 1616 W. Bender Blvd, Hobbs, NM 88240	Telephone No. 575-408-0073	
Facility Name: Central Drinkard Unit	Facility Type: Water Injection Valve Box	
Surface Owner: Carl Coy	Mineral Owner: E.O. Carson	API No. N/A

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	28	21S	37E	589				Lea

Latitude 32.264373N Longitude -103.102874W

### NATURE OF RELEASE

Type of Release: Spill	Volume of Release: 40 BBLS	Volume Recovered: 2 BBLS
Source of Release: Hole in injection line on valve box	Date and Hour of Occurrence: 6/11/06: 01:00 PM	Date and Hour of Discovery: 06/11/06: 01:00 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Maxie Brown	
By Whom? Amy Barnhill	Date and Hour: 06/11/06: 03:00 PM via phone	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

Tee on injection line developed a hole in the valve box.

Describe Area Affected and Cleanup Action Taken.\*

Vacuum truck was called to pick up fluid in secondary containment and ground. Sampling was performed, excavated approx. 2' to ensure no further saturation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Josepha DeLeon	Approved by Environmental Specialist: 	
Title: HES Specialist - Compliance Support - Environmental	Approval Date: 06/27/2016	Expiration Date: 08/27/2016
E-mail Address: jdxdc@chevron.com	Conditions of Approval: Discrete samples only. Delineate and remediate per NMOCD guidelines.	
Date: June 21, 2016	Phone: 432-425-1528	Attached <input type="checkbox"/> IRP 4321

\* Attach Additional Sheets If Necessary

nJXK1617931164

pJXK1617931269