

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**REVIEWED**

By Kristen Lynch at 2:59 pm, Aug 15, 2016

Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company: Renegade Well Services	Contact: Matt Cavanna	
Address: PO Box 840, Denver City, TX 79323	Telephone No. (806) 893-7025	
Facility Name: NHU 13-141	Facility Type: Well	
Surface Owner: Chris Seed	Mineral Owner	API No. 30-025-05437

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	13	18S	37E					Lea County, NM

Latitude N 32.74204° Longitude W 103.21117°

**NATURE OF RELEASE**

Type of Release Produced water	Volume of Release 60 bbls	Volume Recovered 50 bbls
Source of Release The flange on the well head was not properly tightened	Date and Hour of Occurrence 07/27/2016	Date and Hour of Discovery
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Maxey Brown- NMOCD	
By Whom? Steve Bishop, Oxy	Date and Hour 07/27/2016	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

The flange on the well head was not properly tightened causing 60 bbls of produced water to spill. A vacuum truck recovered 50 bbls of water and the flange was tightened.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 126' x 128' both on and off location. Remediation will be completed in accordance with a remediation plan approved by NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Matt Cavanna	Approved by Environmental Specialist: 	
Title: Denver City Yard Manager	Approval Date: 8/15/2016	Expiration Date: 10/15/2016
E-mail Address: mjcavanna@gmail.com	Conditions of Approval: Discrete Samples Only; Delineate and Remediate Per NMOCD Guidelines	Attached <input type="checkbox"/> IRP- 4396
Date: 8/10/16	Phone: (806) 896-7025	

\* Attach Additional Sheets If Necessary

nKL1622852905  
pKL1622853608