

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**RECEIVED**

By JKeyes at 7:24 am, Aug 31, 2016

Form C-141  
August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company	Robinson Oil	Contact	Jason Robinson
Address	P.O. Box 1829	Telephone No.	432-234-8714
Facility Name	Wallen Tonto Federal 19-1 Battery	Facility Type	Tank Battery

Surface Owner	BLM	Mineral Owner		API No.	3002525371
---------------	-----	---------------	--	---------	------------

**LOCATION OF RELEASE**

Unit Letter K&N	Section 30	Township 19S	Range 33E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
--------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude 32.627550 Longitude -103.703716

**NATURE OF RELEASE**

Type of Release	Produced Water/Crude oil	Volume of Release	350/50	Volume Recovered	240/20
Source of Release		Date and Hour of Occurrence	8/23/16 @ unknown	Date and Hour of Discovery	8/24/16 @ 8 a.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	NMOCD and BLM		
By Whom?	Robbie Runnels	Date and Hour	8/24/16 12:45		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Lightning struck battery and caused tanks to rupture. Vacuum trucks were dispatched to recover fluids on surface.

Describe Area Affected and Cleanup Action Taken.\*

Vacuum trucks recovered approximately 260 barrels of fluid. About 200 square feet of pasture was impacted. Most of release contained inside secondary containment. Site will be remediated once work plan is approved.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:  


Printed Name: Robbie Runnels (acting agent for Robinson Oil)

Title: Project Manager

E-mail Address: rrunnels@basinenv.com

Date: 8/26/2016 Phone: 575-396-2378

**OIL CONSERVATION DIVISION**

Approved by Environmental Specialist: 

Approval Date: 08/31/2016

Expiration Date: 10/31/2016

Conditions of Approval:  
Discrete samples only. Delineate and remediate per NMOCD guidelines. Ensure BLM concurrence/ approval.

Attached   
IRP 4424

\* Attach Additional Sheets If Necessary

nJXK1624426331  
pJXK1624426423