## **REVIEWED**

By Kristen Lynch at 8:58 am, Sep 27, 2016

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 State of New Mexico Energy Minerals and Natural Resources District II
811 S. First St., Artesia, NM 88210
District III

Form C-141 Revised August 8, 2011

1220 South St. Francis Dr.

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Oil Conservation Division 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 Santa Fe, NM 87505

			Kel	ease Notino	catio	n and Co	orrective A	ctioi	n				
			OPERA'	ГOR		9 Initi	al Report	T-A	Final Repor				
		anguard Ope		Contact : Chuck Johnston									
Address: 40			Telephone No. 432-202-4771										
Facility Nar	me: Hill 00	Facility Type: Tank Battery											
Surface Ow	ner	Owner	API No. 30-025-06394						<del></del>				
				•		NOEDE	LEACE.						
Unit Letter	Section	Township	Range	Feet from the		N OF RE	Feet from the	L Cont/		Country			
B 04 21 S 37E 3300						N 1700		East	East/West Line County Lea				
Latitude32.5131683Longitude,-103.1650925													
NATURE OF RELEASE													
Type of Release: Oil and Produced waterr							Volume of Release: 100 bbls Wolume Recovered: 100 bbls of produ water and 15 bbls of oil water, 15 bbls of oil and rain water						
Source of Re	lease: Light		lour of Occurrence		water, 15 bbls of oil and rain water Date and Hour of Discovery 9-16-2016								
							16-2016 2:36 am						
Was Immediate Notice Given?  ☐ Yes ☐ No ☐ Not Required							If YES, To Whom? George with OCD Hobbs						
By Whom? J		Date and Hour: 9-16-2016 7:00 am											
Was a Water	course Read	If YES, Volume Impacting the Watercourse.											
If a Watercou	If a Watercourse was Impacted, Describe Fully.*												
Describe Cause of Problem and Remedial Action Taken.*													
Lightning struck tank causing a fire which damaged all the tanks on site. Produced water and oil remained inside of the lined containment. Wells were shut in until weather permits repairs.													
Describe Are	a Affected a	and Cleanup A	Action Tak	en.*									
Damage was and the liner	to tank and replaced if c	equipment in:	side of cor	itainment. Tanks	will be	removed and	replaced. Any co	ntamin	ated soil ab	ove the line	will be	e remediated	
	reprieed if (	samabou.											
I hereby certi:	fy that the i	nformation gi	ven above	is true and compl	lete to 1	he best of my	knowledge and u	nderstar	nd that purs	uant to NM(	OCD ru	les and	
regulations al	l operators :	are required to	report an	d/or file certain re	elease r	otifications an	d perform correct	tive acti	ions for rele	ases which	may en	danger	
public health	or the envir	onment. The	acceptanc	e of a C-141 repo	rt by th	e NMOCD ma	orked as "Final Re on that pose a thre	port" d	oes not reli	eve the open	ator of	liability	
or the environ	ment. In a	ave taned to a ddition. NMO	CD accen	ance of a C-141 i	emediai renort d	le contamination loes not relieve	on that pose a thre the operator of r	at to gr esnonsi	ouna water, bility for co	, surrace war moliance w	er, nun	nan health	
federal, state,	or local lav	vs and/or regu	lations.				vano operato, or r	• <b>op</b> • · · · ·	only tol co	mpnanee m	iai aiy	ouic,	
000 01							OIL CONSERVATION DIVISION						
Signature: /	lht	12	4			1/ 0							
		Approved by Environmental Specialist:											
Printed Name: Chuck Johnston									•				
Title: EHS	Title: EHS						Approval Date: 9/27/2016 Expiration Date: N/A						
435,202-4771						Conditions of Approval: N/A							
						Attached 1 1RP 4450							
Date: 9-19-2		te If Necess		Phone:						1101	1150		