District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

REVIEWED By Kristen Lynch at 8:55 am, Sep 28, 2016

Form C-141 Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

nKL1627227078 pKL1627231767

i i bi e na ser i honoren en loren e en norme e anne en			Rele	ease Notifica	tior	and Co	orrective A	ction		tegetenne dese kilon min kild ford filt for	na na tini ni kaolah yang bana	n an an ann an an an ann an ann an ann an a	
						OPERA	FOR		🖂 Initial Report 🛛 Final Rep			Final Report	
						Contact Christine Alderman							
							Telephone No. 432-853-7059						
Facility Name Laguna Deep 16						Facility Type production							
Surface Owner Mineral Owner							API No. 30-025-38556					5	
				LOCAT	1 O ľ	N OF REI	LEASE						
Unit Letter	Section	Township	Range	Feet from the 1	lorth/	South Line	Feet from the	East/W	est Line	County			
К	36	198	33E	1980		S	1950		W	Lea			
Latitude_32.61484_Longitude -103.61898													
NATURE OF RELEASE													
Type of Release Produced water							Volume of Release 251 bbls Volume Recovered 0						
Source of Release Fiberglass water tank burned							Date and Hour of Occurrence			Date and Hour of Discovery			
						9/17/2016			9/17/2016				
Was Immediate Notice Given?						If YES, To Whom? Kristen Lynch							
By Whom? Gloria Garza							Date and Hour 9/18/2016 11:18 am						
Was a Watercourse Reached?							If YES, Volume Impacting the Watercourse.						
🗌 Yes 🖾 No													
Describe Cause of Problem and Remedial Action Taken. Fiberglass water tank was struck by lightning during a storm. All fluids stayed within a LINED intact plastic liner. Describe Area Affected and Cleanup Action Taken Liner was inspected after the fire and was found to have no damage. All fluids were burned and/or contained.													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
AL. F. AD.						OIL CONSERVATION DIVISION							
Signature: Christine alderman						Approved by Environmental Specialist							
Printed Name: Christine Alderman						Approved by	Environmental Sp	pecialist:	t:				
Title: ESH S	Title: ESH Supervisor					Approval Date: 9/28/2016			Expiration Date: N/A				
E-mail Address: calderman@cimarex.com					(Conditions of Approval: N/A				Attached		**************	
Date: Phone: 432-853-7059									1RP 4456				

* Attach Additional Sheets If Necessary